

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form Approved
Budget Form No. 42-R-421
5. LEASE DESIGNATION AND SERIAL NO.

SF-077874

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Aztec Oil & Gas Company	8. FARM OR LEASE NAME Hanks
3. ADDRESS OF OPERATOR P. O. Drawer 570, Farmington, New Mexico	9. WELL NO. #9
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1110 FSL & 930 FEL Section 5-27N-9W	10. FIELD AND POOL, OR WILDCAT South Blanco Pictured Cliffs
14. PERMIT NO.	11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Section 5-27N-9W
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6433 Gr	12. COUNTY OR PARISH San Juan
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	


SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☒	ABANDONMENT* ☐
(Other) ☐	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- 8-23-71 Pulled tubing. Cleaned out to 2504'.
- 8-24-71 Ran packer, set @ 2332'. Ran 1000 gals HF-Hcl 15% double strength acid. Went on vacuum. Shut in for 3 hours. Swabbed well. Blowing to clean.
- 8-25-71 Pulled packer. Ran 116 joints 1" tubing 2432' landed @2439'. Rig down.



18. I hereby certify that the foregoing is true and correct

SIGNED _____

TITLE District Superintendent DATE September 9, 1971

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

