

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**
Sundry Notices and Reports on Wells

1. **Type of Well**
OIL

2. **Name of Operator**
John F. Staver

3. **Address & Phone No. of Operator**

4. **Location of Well, Footage, Sec., T, R, M**

990' FSL and 1830' FWL; Sec. 3, T-27-N, R-17-W
Unit N

5. **Lease Number**
I-89-IND-57

6. **If Indian, All. or
Tribe Name**

7. **Unit Agreement Name**

8. **Well Name & Number**
Table Mesa #19

9. **API Well No.**
30-045-06805

10. **Field and Pool**

11. **County & State**
San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

A-Plus Well Service Inc., as contractor, re- entered and then plugged and abandon this well per the attached report.

This work was done for the NMOCD Aztec District Office, contract pending.

14. I hereby certify that the foregoing is true and correct.

Signed William F. Clark Title Contractor Date 3/10/99
William F. Clark

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____
CONDITION OF APPROVAL, if any:

A - PLUS WELL SERVICE, INC.

P.O. BOX 1979
FARMINGTON, NM 87499
505-325-2627 • FAX: 505-325-1211

March 2, 1999

Oil Conservation Division

State of New Mexico
1000 Rio Brazos Road
Aztec, NM 87410

Re: Plug & Abandonment Report **Table Mesa #19 Well**
SW, 3, 27N, 17W
San Juan County, NM

Cementing Summary:

Plug #1 with 17 sxs Class B cement inside 4" casing from 1325' to 1137' to cover Dakota top.

Plug #1b with 7 sxs from 1190' to 1140' to cover Dakota top.

Plug #2 with 24 sxs Class B cement inside casing from 510' to 303' to cover Gallup top.

Plug #3 with 28 sxs Class B cement inside casing from 160' to surface, circulate good cement to surface.

Plugging Summary:

2-24-99 Road rig to location, RU. Unable to NU, collar bad. Fenced off pit. SDFD.

2-25-99 Safety Meeting. PU 10' sub and 5-1/2" Fullbore packer. Set packer at 10' and weld on 5-1/2" collar; release packer. NU BOP and test. PU 4-3/4" drill bit with 1 3-1/8" drill collar and 38 joints 2-3/8" tubing; TIH to tag top of 4" liner at 1237'. Circulate hole clean with 30 bbls water. TOH with tubing and LD 4-3/4" bit. PU 3-1/2" bit and TIH to tag at 1325'. TOH with tubing and LD 3-1/2" bit. TIH with open ended tubing to 1301'. Plug #1 with 17 sxs Class B cement inside 4" casing from 1325' to 1137' to cover Dakota top. TOH and WOC. SI well, SDFD.

2-26-99 Safety Meeting. TIH with tubing and tag cement at 1190', cement had fallen back. Pressure test casing to 500#, held OK. Load casing with water. Plug #1b with 7 sxs from 1190' to 1140' to cover Dakota top. PUH. Plug #2 with 24 sxs Class B cement inside casing from 510' to 303' to cover Gallup top. TOH and LD tubing. RU A-Plus wireline truck. Perforate 3 HSC squeeze holes at 100'. Attempt to establish rate into squeeze holes, pressured up to 500#, unable to establish circulation. TIH with tubing to 160'. Plug #3 with 28 sxs Class B cement inside casing from 160' to surface, circulate good cement to surface. TOH and LD tubing. Dig out wellhead and cut off. Found cement down 3' in 5-1/2" casing. Mix 6 sxs Class B cement, fill 5-1/2" casing and install P&A marker. Shut in well and SDFD.
Charlie Perrin with NMOCD on location and approves plugging plan.

3-1-99 Safety Meeting. RD rig and equipment, move off location.

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

14632

Rig No 6

Date 2-24-99

Well No TABLE MESH #19 Location Sec 3, T27N, R17W Company NIMOLCO
TABLE MESH P/A Project

[illegible]

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12	96289	
Operator	Sam Stuart	20		4
Helper	Victor Celis			4
Helper	Robert Velasquez			4
Helper				5

7

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

14635

Date 2-25-99

Well No. TA322 MESA #19 Location Sec 3, T27N, R17W Company NMOC D
TA322 MESA P/H Project

FROM	TO	DESCRIPTION OF OPERATION
5:30	5:45	load supplies
5:45	7:00	DRIVE TO LOC. Held safety meeting (foot protection)
7:00		Pick-up 10' sub, + 5 1/2 full bore packer
		set packer 10', weld on 5 1/2 collar
	9:00	Release packer, RU P.T. 105, NU BOP + lost
9:00		Pick-up 4 3/4 w/ 1 3/8 Drill collar, pick-up 3 5/8
	9:45	its 2 3/8 tag top of 4' liner at 1237'
9:45	10:15	circulate hole clean w/ 30 BBLS
10:15	10:45	POOH w/ 19 stans lay down DC + 4 3/4 bit
10:45		Pick-up 3 1/2 bit, T1H w/ 19 stans, pick-up 4 1/2
	11:15	tag w/ 17' stick-out tag at 1325'
11:15	11:45	POOH w/ 20 stans, lay down 3 1/2 + 3 1/2 bits
11:45	12:30	T1H w/ 3 plugging sub, 4 1/2 its to 1301'
12:30		load hole Pump Plug #1 w/ 17 B-cement 15-4"
	1:00	(1325-1137) TOL 1137
1:00		lay down 5 1/2 standback 10 stans
	1:30	load hole WOC
1:30	2:00	drain-up SDFID

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment 4 3/4 + 3 1/2 Acc. Cement Retainers 5 1/2 DHS Packer

Cementing Plug #1 175xs

Wireline _____

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12	96409	
Operator	Sam Stuart	20		8 1/2
Helper	Victor Celis			8 1/2
Helper	Robert Velasquez			8 1/2
Helper	Dennis Heasley	141		9 1/2

Rig No 6

Date 2-26-99

Well No. TABLE MESA #19 Location _____ Company NMUCD
TABLE MESA P/A Project

[illegible]

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing Plug #1B 75xs Plug #2 245xs Plug #3 285xs Plug #4 1100xs 65xs

Wireline ① 100' 3-3 1/8 HSC

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12	96569	
Operator	Sam Stuart 143	20		9 1/2
Helper	Victor Celis			8
Helper	Robert Velasquez			8
Helper	Doug Hearn	141		9 1/2

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

14635

Rig No 6

Date 3-1-99

Well No. TABLE Mesa # 19 Location Sec 3, T27N, R17W Company NMOCID
TABLE Mesa P/A Project

[illegible]

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing

Wireline

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	Bill Randall	12		
Operator	Sam Stuart	20		3
Helper	Victor Celis			3
Helper	Derry Hearn			3
Helper				