

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 078935

Unit Santa Fe No. 2

JUL 1 1951

OIL CON. COM.
DIST. 3

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 30, 1951

Well No. 2 Thompson is located 990 ft. from SW line and 990 ft. from E line of sec. 2

SE 1/4, Sec. 2 T-27N R-12W NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
West Kutz San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5983 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded on June 27, 1951. 100' 8 5/8" casing was cemented with 75 sacks. On June 28th prior to drilling plug, casing tested 500# for 30 minutes with no drop in pressure. Plug was drilled and fluid level was checked for 30 minutes with 500# with no drop.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.


Company Danube Oil Company

Address 213 First National Bank Building

Amarillo, Texas

By [Signature]

Title Agent



(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE IN FIELD	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASINGS
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REPAIRING OR REPAIR
NOTICE OF INTENTION TO SHUT OFF	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR REEL CASINGS	ON PERMANENT WELL HISTORY
NOTICE OF INTENTION TO WIDEN WELL	

(Indicate above by check the nature of report, notice or other data)

The elevation of the datum floor above sea level is _____ ft.

The _____ line and _____ ft. from _____ line of _____

_____ (Name of landowner)

_____ (Name of lessee)

DETAILS OF WORK

(State nature and extent of work, and location of proposed casing; indicate by check the nature of work, and an other important proposed work)

I, _____, of _____, do hereby certify that the above is a true and correct copy of the original report on file in the _____, and that the same has been examined and found correct.

I understand that this plan of work must receive approval in writing by the Geological Survey before it can be carried out.

Company _____

Address _____

By _____

[Signature]

Date _____