

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 078936

Unit SW/4 Sec. 2, T27N, R12W

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 27, 1951

Well No. 1 Harmon is located 1650 ft. from N line and 1650 ft. from E line of sec. 2

SW/4 Sec. 2

T-27N, R-12W

NMEX

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

West Ruts Canyon

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 5941 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded July 21, 1951. 90' of 8-5/8" casing was cemented with 90 sacks. On July 22nd prior to drilling plug, casing tested 500# for 30 minutes with no drop in pressure. Plug was drilled and fluid level was checked for 30 minutes with 500# with no drop.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Danube Oil Company

Address 213 First National Bank Building

Artesillo, Texas

By

Title Agent