Form 9-331

TEST WATER SHUT-OFF

FRACTURE TREAT

REPAIR WELL

SHOOT OR ACIDIZE

UNITED STATES

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBMIT IN TRIPLICATE*

Form approved. Budget Bureau No. 42-R1424

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

	DEPARTMENT OF THE INTERIOR (Other Instructions on re GEOLOGICAL SURVEY		
SUNDRY NOTION (Do not use this form for proposition "APPLICA"	G. IF INDIAN, ALLOTTRE OR TRIBE NAME		
I. OIL GAS X OTHER	Shut in	7. UNIT AGREEMENT NAME	
DEPCO, Inc.		8. FARM OR LEASE NAME Mudge "A"	
	Building, Denver, CO 80202	9. WELL NO.	
4. LOCATION OF WELL (Report location ele See also space 17 below.) At surface	arly and in accordance with any State requirements.	W. Kutz, P.C.	
1650' FSL, 990' FWL		L, Sec. 6, T27N, R11	
14. PERMIT NO.	GR 6098 GR, RT, GR, etc.)	San Juan NM	
16. Check Ap	propriete Box To Indicate Nature of Notice, Report, or		
NOTICE OF INTENT	ENT REPORT OF:		

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

WATER SHUT-OFF

(Other) .

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

Mudge "A" No. 7 has been in a temporary abandoned status since November, 1968.

DEPCO, Inc., requests approval to retain temporary abandoned status pending evaluation of results obtained by redrilling well in 160 acre spacing unit, NE, Sec. 12, T27N, R12W, San Juan County, New Mexico.

4					······································
18. I hereby certify that the forcesing is true and correct SIGNED	Dist.	Prod.	Supt.		DATE 2-1-75
(This space for Federal or State (piece use)	<u> </u>				
APPROVED BY	TITLE			- 10	DATH