(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office Senta Fe
Lease No. 079116
Unit 160

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		September 13, 1951 , 19		
Well No.3 is	located 1650ft.	from $\{S\}$ line a	and 1650 ft. from	ne of sec. 1
31 been 1	27%	124	n. g. p. u.	
(¼ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
West Kuts Conyon	Sma_Ju	San Juan)
(Field)	(Cor	unty or Subdivision)	(State or Te	rritory)

The elevation of the derrick floor above sea level is 6027.6ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, comenting points, and all other important proposed work)

Run 10% ft. 10" surface casing on September 1, 1951. Communication with 75 seeks. Communication of surface. Pressured up and held.

Ram 1725' 7" 17% easing on September S, 1951. Commuted with 100 sacks. Prescuredup and held. Job o.k.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company JACE D. HANCOCK & COMPANY, LTD.

Address 916 Kirby Building

By O. F. Milliang

Title Asst. Supt.

Total 16-8437-4