(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Santa	7e
Land Office		

Lease No. SF 079116

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLSOIL CON. COM

OTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY	
------------------------------------	---	--

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		Oct	eber 22, 1951	, 19
Well No. 3 is locat	ed 1650 ft.	from $\begin{cases} N \\ S \end{cases}$ line as	nd 1650 ft. from W	line of sec. 1
Swi Sec. 1	271	124	N.N.P.N.	
(¼ Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
West Ests Conyon	San Jan	n	New Mexi	·
(Field)	(Co	unty or Subdivision)	(State	or Territory)

The elevation of the derrick floor above sea level is 6027.6 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, comenting points, and all other important proposed work)

Well shot on October 9, 1951 from 1740° to 1821° with 400 qts. solidified mitro. Shot temped with gravel and Calseel. Work done by Atlas Glycerine Company. Well tested 1,400 MCF before shot, and 3,400 MCF after shot.

1810° of 1° line pipe set in well. Christmas tree installed. Well completed 10-1k-51.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.			
Company 3	MES D. MANCOCK & COMPANY,	LTD.	
	6 Kirby Bailding		
De	llas, Texas	By O. F. Stenens	
ec: M OI	L COMMENTATION COMMISSION	Title Asst. Supt.	

