


COPY FOR
STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
SUBMIT IN TRIPLICATE TO
DISTRICT OFFICE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078938
Unit NW/4 Sec. 2

SUNDRY NOTICES AND REPORTS ON WELLS



NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	DIST. <u>X</u>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 30, 1951

Well No. 2 Harmon is located 1650 ft. from N line and 1650 ft. from W line of sec. 2

<u>NW/4 Sec. 2</u> (1/4 Sec. and Sec. No.)	<u>2N</u> (Twp.)	<u>12W</u> (Range)	<u>NMPM</u> (Meridian)
<u>West Kutz Canyon</u> (Field)	<u>San Juan County</u> (County or Subdivision)	<u>New Mexico</u> (State or Territory)	

The elevation of the derrick floor above sea level is 5931 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

Rotary tools were used from the surface to a total depth of 1601' where 1601' of 5 1/2" casing was cemented with 100 sacks. The plug was pumped down and tested for 2 hours with no drop in pressure.

Cable tools were moved on 8-28-51, the hole was bailed dry, the plug drilled, and tested for 2 hours and it was found that the hole was dry and that a satisfactory cement job was had. The hole was drilled to a total depth of 1693, and the well showed an estimated 1 million cubic feet of gas at 1615, at which point the hole was loaded with water.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Danube Oil Company
Address 213 First National Bank Building
Amrille
Texas
By _____
Title Agent