

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Butte, Pa.
Lease No. 7-6734
Unit Block

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 10, 1951


Well No. 150 is located 11 ft. from N line and 5 ft. from E line of sec. 36
NE 1/4 Section 36 (1/4 Sec. and Sec. No.) T-27N (Twp.) R-4E (Range) N.M.P.M. (Meridian)
Butte Dakota (Field) Butte Co. (County or Subdivision) Montana (State or Territory)

The elevation of the derrick floor above sea level is 6143 ft. O.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded 8/7/51
Set 10 jcs., 2 1/2" casing, landed at 331' with 275 ex. c.t.
Tested casing with 500 psi pressure for 30 minutes. No leak.
Drilled cement 8/9/51
Tested with 500 psi pressure for 30 minutes.
No leak in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Astec Oil & Gas Company

Address Box 570
Butte, Montana

ORIGINAL SIGNED BY JOE C. SALMON

By J. C. Salmon

Title District Superintendent

