


(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079116
Unit 250



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 7, 1951

Bancroft
Well No. 2 is located 770 ft. from N line and 770 ft. from 1/2 W line of sec. 1
1/4 Sec. 1 27N 12W R.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
East Kats Canyon San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevations of the ~~surface~~ above sea level is 6001.3 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

December 4, 1951: Topped pictured cliffs formation at 1719'. Set 1725'
7" 17# casing. Cemented with 100 sacks.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company James D. Bancroft & Co. Inc.

Address 716 Kirby Bldg.

Dallas, Texas

By C. F. Stevens

Title Assistant Superintendent

cc - H.M. Oil Conservation Commission (2)