

(SUBMIT IN TRIPLICATE)

Land Office Santa Fe

Lease No. 078902

Unit _____

Lilly Lease

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 3, 19 52

(Lilly)

Well No. 1 is located 692 ft. from N line and 877 ft. from E line of sec. 4

NE/4 Sec. 4
(1/4 Sec. and Sec. No.)

27N
(Twp.)

11W
(Range)

NMPM
(Meridian)

West Kuts

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)


The elevation of the derrick floor above sea level is 5786 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10/3/52 TD 114' 9/ 5/8" casing cemented at 113', with 60 sacks cement circulated to the surface.

Pressured up on casing to 500#
No pressure drop in 30 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Benson and Montin

Address 315 1/2 West Main St.

Farmington, N. M.

By Albert R. Greer

Title Field Sup't.

OIL CONSERVATION COMMISSION
AZTEC DISTRICT OFFICE

No. Copies Received 2

DISTRIBUTION

	NO. FURNISHED	
Operator		
Santa Fe	<u>1</u>	
Proration Office		
State Land Office		
U. S. G. S.		
Transporter		
File	<u>1</u>	✓