

(SUBMIT IN TRIPLICATE)

Indian Agency Mountain Park ✓

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Arizona

Allottee _____

Lease No. 14-22-022-2179

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 4, 1958

Well No. 1 Barro is located 660 ft. from N line and 660 ft. from W line of sec. 6

SW/4 NW/4 Sec. 6 T. 27 N. - R. 14 W. 1820
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3717 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well plugged as follows:

2723 to 2400

2400 to 2200

1100 to 1000

800 to 700

20 sacks at base of surface pipe (136')

3 sacks at surface

Pits filled.

Location cleaned and grouted and water arrested, and is now ready for your inspection.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DAVIS OIL COMPANY

Address 1000 Highland Springs Blvd.

Durham 2, Colorado

By Paul Messinger
Title Asst. Engr., Southern Div.