

OIL CONSERVATION COMMISSION
P. O. BOX 871
SANTA FE, NEW MEXICO

April 19, 1957

El Paso Natural Gas Company
P. O. Box 997
Farmington, New Mexico

Attention: Mr. E. J. Coel

Administrative Order NSL-100

Gentlemen:

Reference is made to your application for approval of an unorthodox well location for your Schwerdtfeger "A" Well No. 9 (PM), to be located 1190 feet from the North line and 654 feet from the East line and in the NE/4 NE/4 of Section 31, Township 28 North, Range 8 West, Blanco Mesa-verde Gas Pool, San Juan County, New Mexico.

It is our understanding that this unorthodox well location is based upon extreme topographic conditions in the NE/4 of said section.


Inasmuch as there are no other affected offset operators, it is possible for immediate approval to be granted. Therefore, by authority granted me under provisions of Section 1 (c) of the Special Rules and Regulations of the Blanco Mesa-verde Gas Pool, as set forth in Order R-110 as amended by Order R-397, you are hereby granted an exception to Section 1 (c) of Order R-110 as amended by Order R-397 for the above described unorthodox well location. You must also obtain like approval from the U. S. Geological Survey.

Very truly yours,

A. L. PORTER, Jr.,
Secretary-Director

ga

cc Oil Conservation Commission - Aztec ✓
USGS-Farmington



1. The first part of the report is a summary of the work done during the last year. It is a very short summary, but it gives a good idea of the work done.

2. The second part of the report is a detailed account of the work done during the last year.

3. The third part of the report is a summary of the work done during the last year. It is a very short summary, but it gives a good idea of the work done.

4. The fourth part of the report is a summary of the work done during the last year. It is a very short summary, but it gives a good idea of the work done.

5. The fifth part of the report is a summary of the work done during the last year. It is a very short summary, but it gives a good idea of the work done.

6. The sixth part of the report is a summary of the work done during the last year. It is a very short summary, but it gives a good idea of the work done.

7. The seventh part of the report is a summary of the work done during the last year. It is a very short summary, but it gives a good idea of the work done.

8. The eighth part of the report is a summary of the work done during the last year. It is a very short summary, but it gives a good idea of the work done.

9. The ninth part of the report is a summary of the work done during the last year. It is a very short summary, but it gives a good idea of the work done.

10. The tenth part of the report is a summary of the work done during the last year. It is a very short summary, but it gives a good idea of the work done.

