

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office 3F  
Lease No. 078566  
Unit 10000

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 20, 1957

Well No. 4 (100) is located 900 ft. from N line and 1650 ft. from E line of sec. 34


<u>Sec. 34</u> (1/4 Sec. and Sec. No.)	<u>23 N</u> (Twp.)	<u>8 E</u> (Range)	<u>N.M.P.M.</u> (Meridian)
<u>So. Blanco P. Co. 3rd. &amp; Blanco</u> (Field)	<u>San Juan</u> (County or Subdivision)	<u>New Mexico</u> (State or Territory)	

The elevation of the derrick floor above sea level is 6270 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud onto 8-11-57.  
On 8-11-57. Total depth 176'.  
Set 4 joints, 10 3/4", 32.75#, "Reco C. W. casing (101') set at 173' with  
125 sacks regular cement circulated to surface.  
Hold 500' 30 Minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Blanco Natural Gas CompanyAddress Box 97Farmington, New MexicoBy Original Signed D. C. Johnston  
Title Petroleum Engineer