

NUMBER OF COPIES RECEIVED		NEW MEXICO OIL CONSERVATION COMMISSION				FORM C-103 (Rev 3-55)	
DISTRIBUTION		MISCELLANEOUS REPORTS ON WELLS					
(Submit to appropriate District Office as per Commission Rule 1106)							
Name of Company El Paso Natural Gas Company				Address P.O. Box 990, Farmington, New Mexico			
Lease Blanco Gas Unit		Well No. 1	Unit Letter A	Section 36	Township 28 North	Range 8 West	
Date Work Performed 3-29-63		Pool Blanco Mesa Verde			County San Juan		
THIS IS A REPORT OF: (Check appropriate block)							
<input type="checkbox"/> Beginning Drilling Operations		<input type="checkbox"/> Casing Test and Cement Job		<input checked="" type="checkbox"/> Other (Explain): See below			
<input type="checkbox"/> Plugging		<input type="checkbox"/> Remedial Work					
Detailed account of work done, nature and quantity of materials used, and results obtained. This well is bridged in the Meneffee section of the open hole. 3-29-63: The 2 3/8" O.D. EUE production tubing was perforated above the bridge with the Kinley tubing perforation (1/4" diameter holes.) One (1) hole at (4046') and one (1) hole at (4355').							
Witnessed by				Position		Company	
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY							
ORIGINAL WELL DATA							
D F Elev.		T D		P B T D		Producing Interval	
Completion Date		Tubing Diameter		Tubing Depth		Oil String Diameter	
Oil String Depth		Perforated Interval(s)		Open Hole Interval		Producing Formation(s)	
RESULTS OF WORKOVER							
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD	
Before Workover							
After Workover							
OIL CONSERVATION COMMISSION				I hereby certify that the information given above is true and complete to the best of my knowledge.			
Approved by Original Signed By A. R. KENDRICK				Name Ben Boyd			
Title PETROLEUM ENGINEER DIST. NO. 3				Position Production Engineer			
Date Apr 3 1963				Company El Paso Natural Gas Company			

