

(SUBMIT IN TRIPLICATE)  
**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

Land Office Santa Fe  
Lease No. 70955-A  
Unit Soval

**SUNDRY NOTICES AND REPORTS ON WELLS**

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 30, 19 51

Well No. 4 is located 1520 ft. from N line and 1090 ft. from W line of sec. 27  
34 SW Section 27 20N 10W T. 1 N. R. 1 E.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Largo Art. San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6273 ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On April 20, 1951:

Run 7" casing using 22 joints of H-40 - 23 lb. (634') on bottom, and 105 joints of 20 lb. new s.s. J-55 on top (3576') set at 4255'. Cemented in two stages.

First stage used 150 sacks Ideal Regular Cement and 1 sack Floccal. Top of cement by Temperature Survey 3660'.

Second Stage used 250 sacks Ideal Regular Cement and 3 sacks Floccal. Top of cement by Temperature Survey 1680'.

Held 1000 pounds for 9 hours OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SAF JAW PRODUCTION COMPANY

Address 102 North Court Avenue

Farmington, New Mexico

By E. J. Coal  
E. J. Coal

Title Petroleum Engineer

Issued October 1964

Form 100-10

Form 100-10

REQUIREMENT IN TRIPLICATE  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUMMARY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF REPAIRS TO WELL
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF ALTERING Casing
NOTICE OF INTENTION TO TEST WATER SHOWN	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO CHANGE PLANNED OPERATIONS	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO INTERFERE WITH OR INFRINGE ON RIGHTS OF OTHERS	SUBSEQUENT REPORT OF WATER SHUT-OFF

THIS FORM IS TO BE CHECKED BY THE FIELD OFFICE OF THE GEOLOGICAL SURVEY

Form 100-10

Well No. 100-10 is located in the State of Texas, County of Tarrant, and is owned by the Texas Eastern Pipeline Company, Inc.

The well is located in the State of Texas, County of Tarrant, and is owned by the Texas Eastern Pipeline Company, Inc.

The location of the well is shown on the map attached hereto.

DETAILS OF WORK

The work was done by the Texas Eastern Pipeline Company, Inc., and the results are as follows:

The work was done by the Texas Eastern Pipeline Company, Inc., and the results are as follows:

The work was done by the Texas Eastern Pipeline Company, Inc., and the results are as follows:

The work was done by the Texas Eastern Pipeline Company, Inc., and the results are as follows: