

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY El Paso Natural Gas Company - Box 997, Farmington, New Mexico
(Address)

LEASE Florance WELL NO. 5-C UNIT N S 30 T 28N R 8W
DATE WORK PERFORMED 11-28-57 POOL South Blanco P. C. Ext. & Blanco M. V.

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☒ Other Sealing leak in casing.

Detailed account of work done, nature and quantity of materials used and results obtained.

Tested for leak with Baker Fallbore retrievable cementer. Found leak between 2322' and 2352'; squeezed with 100 sacks Neat cement. Maximum and final pressure 2000 $\frac{1}{2}$.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:


DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test _____
Oil Production, bbls. per day _____
Gas Production, Mcf per day _____
Water Production, bbls. per day _____
Gas-Oil Ratio, cu. ft. per bbl. _____
Gas Well Potential, Mcf per day _____
Witnessed by _____



(Company)

OIL CONSERVATION COMMISSION

Name Original Signed Emery C. Arnold
Title Supervisor Dist. # 3
Date JAN 30 1958

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Original Signed D. C. Johnson
Position Petroleum Engineer
Company El Paso Natural Gas Company

OIL CONSERVATION COMMISSION	
AZTEC DISTRICT OFFICE	
No. Copies Received	3
DISTRIBUTION	
Operator	1
Santa Fe	1