

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Po
Lease No	07955-A
Unit	

SUNDRY NOTICES A	ND REPORTS ON WELLS
NOTICE OF INTENTION TO DRILL	
NOTICE OF INTENTION TO CHANGE PLANS.	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT.
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL.	
(INDICATE ABOVE BY CHECK MARK I	NATURE OF REPORT, NOTICE, OR OTHER DATA)
	, 19-53
Well No is locatedft. from	$\begin{bmatrix} N \\ S \end{bmatrix}$ line and $\begin{bmatrix} E \\ W \end{bmatrix}$ line of sec.
(TW)	Rema.
(County of	r Subdrivision) (State of Turney)
The elevation of the derrick floor above sea leve	el is ft.
DETAIL	S OF WORK
State names of and expected depths to objective sands; show sizes	s, weights, and lengths of proposed casings; indicate mudding jobs, coment- ner important proposed work)
	and important proposed work)
Oc April 30, 1951:	
Shot wall with ANO quarts 6.2.0	. from 3060' to 8660'.
30 gage teles on the gas.	
•	
T. D. 4658	
I understand that this plan of work must receive approval in wr	riting by the Geological Survey before operations may be commenced.
Company Company	
Address Avenue	-0 - 1
Paratagine, New Yorking	By
	Title 5. Com
	TOWNS AND LONG.

S. S. GOVERNMENT PRINTING DEFICE 18-0497...4