

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078565-A
Unit Graveling

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 25, 1951

Well No. 2-A is located 990 ft. from Y line and 990 ft. from W line of sec. 22

SW 1/4 SW 1/4 Section 22 26N 6W N. M. P. M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Largo Ext. San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the ground ~~derrick floor~~ above sea level is 5913 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

February 24, 1951

Set 7" casing using 23# N-80, 988' on bottom, and 20# J-55, 2963' set at 3945' with two stages of cement.

First stage (tool at 3338') 125 sacks and 4 sacks Strata Seal, circulated same to surface. Second stage used 550 sacks with 40 sacks Strata Seal, mixed on top.

Ran temperature survey - no sign of cement above 3338'. Top of cement 3338'.

Held back for 12 hours.

I understand that this plan must receive approval in writing by the Geological Survey before operations may be commenced.

Company SAN JUAN PRODUCTION COMPANY

Address 102 1/2 NORTH COURT AVENUE

FARMINGTON, NEW MEXICO

By E. J. Coal

Title Petroleum Engineer