(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No 078499



SUNDRY NOTICES AND REPORTS ON WELL

OIL CON. COM. SUBSEQUENT REPORT OF WATER SHUT-OFF... NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... SUBSEQUENT REPORT OF ALTERING CASING..... SUBSEQUENT REPORT OF REDRILLING OR REPAIR NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL. NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... SUPPLEMENTARY WELL HISTORY..... NOTICE OF INTENTION TO PULL OR ALTER CASING.....

(INDICAT	E ABOVE BY CHECK MA	RK NATURE OF REPO	RT, NOTICE, OR OTHER DATA)	
		Farmingto	n, New Mexico	Oct. 10	19 51
Well No. Tapp #1 is loc	ated .1715.ft.	from $\binom{N}{S}$ line a	and 1100 ft. from	$\left\{\begin{array}{c} \mathbf{E} \\ \mathbf{v} \end{array}\right\}$ line of sec.	55
ME/4 of 22 (M Sec. and Sec. No.)	28 <u>N</u>	(Range)	MIZE (Meridian)		
Blanco-Ia Plata (Field)		Juan nty or Subdivision)	Herr Lies (Str	ricoate or Territory)	
The elevation of the derrick	Level Loor above sea	level is 5891	_ ft.		
	DET	AILS OF WO	RK		
State names of and expected depths to		sizes, weights, and l ll other important p		ndicate mudding jobs	, cement-
3-9-51 Oral approval 1	was given to	drill this	well in with gas	3.	

I understand that this plan of work must receive approval in writing by the	Geological Survey before operations may be commenced.
Company Three States Haturel Gas Company	
Address 11th Floor	
Tower Petroleum Building	Ву
Dallas 1, Texas	James Woodard Title Agent