

Case No. 078499-A

Line:

|                                                  |                                       |                                            |                                                                                                                                                                                                      |
|--------------------------------------------------|---------------------------------------|--------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| NOTICE OF INTENTION TO REPAIR                    | <input checked="" type="checkbox"/> X | SUBSEQUENT REPORT ON WATER SHUT OFF        | <div style="text-align: center;"> <div style="font-size: 2em; font-weight: bold; letter-spacing: 0.5em;">R E C E I V E D</div> <div style="font-size: 1.5em; font-weight: bold;">JUN 21</div> </div> |
| NOTICE OF INTENTION TO DEMOLISH PLANS            | <input type="checkbox"/>              | SUBSEQUENT REPORT ON DRAINING OR ACIDIZING |                                                                                                                                                                                                      |
| NOTICE OF INTENTION TO DISCONNECT WATER SHUT OFF | <input type="checkbox"/>              | SUBSEQUENT REPORT ON WATER RUNNING         |                                                                                                                                                                                                      |
| NOTICE OF INTENTION TO REPAIR OR REPAIR WELL     | <input type="checkbox"/>              | SUBSEQUENT REPORT ON REPAIRING OR REPAIR   |                                                                                                                                                                                                      |
| NOTICE OF INTENTION TO REPAIR OR ACTION          | <input type="checkbox"/>              | SUBSEQUENT REPORT ON REPAIRING             |                                                                                                                                                                                                      |
| NOTICE OF INTENTION TO DISCONNECT WATER SHUT OFF | <input type="checkbox"/>              | SUBSEQUENT REPORT ON REPAIRING             |                                                                                                                                                                                                      |

RECEIVED

JUN 21 1962

U. S. GEOLOGICAL SURVEY  
FARMINGTON, NEW MEXICO

June 21

Hardie "E"  
Well No. 3 3900 1750  
NE/4 Sec. 23 28N 8W N.M.F.M.  
Blanco Mesa Verde San Juan New Mexico

The elevation of the deck top above sea level is 6258 ft.

### DETAILS OF WORK

**It is intended:** \_\_\_\_\_

It is intended to mud drill a well with rotary tools to approximately 2933', set intermediate casing, then gas drill thru the Mesa Verde formation, and to perforate and fracture possible producing zones. Est. T. D. 5180'.

Casing Program:

- 9 5/8" @ 300' w/210 sks. cement circulated to surface.  
7" at 2933' w/155 sks. cement to cover Fruitland.  
4 1/2" @ 5130' w/225 sks. cement to cover top of liner.

The E/2 of Section 23 is dedicated to this well.

A circular ink stamp with the word "RECEIVED" at the top, the date "JUN 22 1962" in the middle, and "OIL CON. COM." and "DIST. 3" at the bottom.

El Paso Natural Gas Company

Box 990

Farmington, New Mexico

Petroleum Engineer

## NEW MEXICO OIL CONSERVATION COMMISSION

Well Location and Acreage Dedication Plat

Section A.

Date MAY 7, 1962

Operator **EL PASO NATURAL GAS COMPANY** Lease **HARDIE "E"** SF078499-A  
 Well No. **3** Unit Letter **B** Section **23** Township **28-N** Range **8-W** NMPM  
 Located **990** Feet From **NORTH** Line **1750** Foot From **EAST** Line  
 County **SAN JUAN** C. L. Elevation **6248** Dedicated Acreage **320** Acrea  
 Name of Producing Formation **MESA VERDE** Pool **BLANCO M.V.**

1. Is the Operator the only owner in the dedicated acreage outlined on the plat for (x)?  
 Yes ☒ No ☐
2. If the answer to question one is "no", have the interests of all the owners been consolidated by communitization agreement or otherwise? Yes ☐ No ☐ If answer is "yes", Type of Consolidation:

3. If the answer to question two is "no", list all the owners and their respective interests below:

Owner

Land Description

RECEIVED

JUN 22 1962

OIL CON. COM.  
DIST. 3

RECEIVED

JUN 21 1962

GEOLOGICAL SURVEY  
NEW MEXICO

Section B.

This is to certify that the information in Section A above is true and complete to the best of my knowledge and belief.

**El Paso Natural Gas Company**

(Operator)


~~ORIGINAL SIGNED E.S. OBERLY~~Original Signed **D.W. Meehan**

Box 990

(Address)

**Farmington, New Mexico**

Note: All distances must be from outer boundaries of section.



This is to certify that the above plat was prepared from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

(Seal)

Farmington, New Mexico

Date surveyed MAY 1, 1962

*David O. Kilmer*  
 Registered Professional Engineer and/or Land Surveyor