



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 013860-A
Unit Russell

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 17, 1958

Well No. 3(PH) is located 990 ft. from Box line and 1140 ft. from Box line of sec. 23
SW Sec. 23 23N 01 N.M.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco & Wildcat San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5075 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

4-20-58. Total Depth 4894'.
 Ran 57 joints 5 1/2", 15.50#, J-55 liner (2357') set from 2442' to 4799' with
 125 sacks regular cement, 125 sacks Pozmix, 6% gel, 1/3# Flocele/sk followed by
 50 sacks regular cement.

Held 1000# for 30 minutes.

Top of cement by temperature survey at 2550'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company H. Paso Natural Gas Company

Address Box 997

Paradigm, New Mexico

Original Signed D. C. Johnston
By _____

Title Petroleum Engineer