STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

May 25, 1984

Mr. Herman McAnaley El Paso Natural Gas Co. P.O. Box 4990 Farmington, NM 87499

Re: San Juan 28-7 Unit #91 B-34-28N-7W San Juan 28-7 Unit #44-A I-17-29N-7W Warren #4 H-14-28N-9W

Dear Herman:

I witnessed packer leakage retests on the referenced wells on 5-24-84. The Warren #4 has a packer or tubing leak. In order to comply with Rule 112-A and the order authorizing the multiple completion, please initiate remedial action as soon as possible.

The San Juan 28-7 Unit #91 and the San Juan 29-7 Unit #44-A were ok.

If you have any questions, please contact this office.

Yours truly,

Charles Gholson

Deputy Oil & Gas Inspector

CG/dj

xc: Well File