

(SUBMIT IN TRIPLICATE)

 UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
Land Office Santa FeLease No. 000112Unit Riddle

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 6, 1956

Well No. 2-F is located 990 ft. from S line and 1070 ft. from W line of sec. 8Section 8

(1/4 Sec. and Sec. No.)

26N

(Twp.)

5W

(Range)

100M

(Meridian)

Blanco

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 5938 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casing, indicate mudlogging jobs, cementing points, and all other important proposed work)

On 1-31-56. Total Depth 2522'.


Ran 80 joints 7", J-55, 20#, casing (2512') set at 2522' with 100 sacks regular cement, 100 sacks Pozmix, 100# floccs and 4# Gel.

Held 1000# 30 minutes.

Top of cement by temperature survey at 1315'.

RECEIVED

FEB 3 1956

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas CompanyAddress Box 997Farmington, New MexicoBy D. L. [Signature]
Title Petroleum Engineer