

			X

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_  
Lease No. **SP-078695**  
Unit \_\_\_\_\_  
**Graham Federal**

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 8, 1960

Well No. **#1** is located **330** ft. from **N** line and **330** ft. from **E** line of sec. **6**

**NE/4 NE/4 Sec. 6**  
(1/4 Sec. and Sec. No.)

**27N**  
(Twp.)

**11W**  
(Range)

**NMPM**  
(Meridian)

**Kuts-Gallup**  
(Field)

**San Juan**  
(County or Subdivision)


**New Mexico**  
(State or Territory)

The elevation of the derrick floor above sea level is **6017** ft. **G.L.**

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

**12/3/60 Spudded 6:30 P.M. in 13 3/4" hole.**  
**Ran & set 10 jts. (323.37') of 10 3/4" 32.50# surface casing @**  
**302' w/200 ex 3% Calcium Chloride. Cement circulated. WOC**  
**12 hours, pressured up w/750# for 30 minutes. Tested OK**



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Southwest Production Company**

Address **162 Petro. Center Bldg.**  
**Farmington, New Mexico**

Original signed by  
By **Carl W. Smith**

Title **Production Supt.**