

4-USGS
1-WD
1-D, 1-F

	X	

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **SF-079114-A**
Unit _____
Campbell Federal

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 19, 1962

Well No. **6** is located **790** ft. from **N** line and **1850** ft. from **W** line of sec. **27**

NE 1/4 NW 1/4 Sec. 27
(1/4 Sec. and Sec. No.)

27 N
(Twp.)

12 W
(Range)

NMPM
(Meridian)

Basin Dakota
(Field)

San Juan
(County or Subdivision)


New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **5835** ft. **GL**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

4/18/62 Spudded in 2:30 p.m. in 13 3/4" surface hole drld. to 251'. Ran & set 9 jts. 231' of 10 3/4" 32.75# Lone Star Casing @ 221' KB w/150 sx cement 2% cc. WOC 10 hrs. pressure test w/700# for 30 minutes. Held OK. Drilling



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Southwest Production Company**

Address **207 Petr. Club Plaza**

Farmington, New Mexico

Original signed by
By **Carl W. Smith**

Title **Superintendent**