


STATE OF NEW MEXICO
**OIL CONSERVATION
 COMMISSION**
 DISTRICT NO. 3
 Phone 99 P. O. Box 697
 AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)
**UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY**

Land Office Santa Fe
 Lease No. 77952
 Unit J. C. Gandy



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Farmington, New Mexico, August 14, 1951

Well No. C-1 is located 2310 ft. from [N] line and 990 ft. from [W] line of sec. 23

23 of Section 23 (1/4 Sec. and Sec. No.)
1-27-N (Twp.) 10-W (Range) 107N (Meridian)
Falcher-Mats (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6227 ft. (G.L.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On August 5, 1951 at 5:00 P.M., 5-1/2" casing was set at 2119 feet with 65 sacks cement. Rotary rig was moved off location and cable tool rig rigged up for drilling cement plug and pay. On August 8, 1951, hole was bailed dry and remained dry for two hours. Thirty-seven feet of solid cement was then drilled in bottom of pipe and hole again bailed dry. Hole remained dry for two hours which was considered a satisfactory water shut-off test.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Stanford Oil and Gas Company

Address Box 487

Farmington, New Mexico

By [Signature]

Title Production Foreman

(SUBMIT IN TRIPlicate)
 UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY

RECEIVED
 DIVISION OF
 WATER RESOURCES
 WASHINGTON, D. C.

SUNDRY NOTICES AND REPORTS ON WELLS

.....	SUBSEQUENT REPORT OF WATER SHUT-OFF
.....	SUBSEQUENT REPORT OF SHOOTING OR RECHARGING
.....	SUBSEQUENT REPORT OF ALTERING CASING
.....	SUBSEQUENT REPORT OF REPAIRING OR REPAIR
.....	SUBSEQUENT REPORT OF ABANDONMENT
.....	SUBSEQUENT REPORT OF REPAIRING OR REPAIR
.....	SUBSEQUENT REPORT OF SHOOTING OR RECHARGING
.....	SUBSEQUENT REPORT OF ALTERING CASING
.....	SUBSEQUENT REPORT OF WATER SHUT-OFF

(INDICATE ABOVE BY CHECKING IN THE COLUMN OF REPORT, SOURCE OF OTHER DATA)

..... is located ft from $\left\{ \begin{array}{l} N \\ S \end{array} \right\}$ line and ft from $\left\{ \begin{array}{l} E \\ W \end{array} \right\}$ line of sec.
 (Town) (Range) (Section)
 (County or Subdivision) (State or Territory)

DETAILS OF WORK

The elevation of the derrick floor above sea level is ft.

.....

I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.
 Comment.....
 Address.....
 By.....
 Title.....

--	--