



STATE OF NEW MEXICO  
ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

November 1, 1991

Mr Paul West  
Union Oil Co of Calif  
3300 N Butler Ste 200  
Farmington NM 87401

RE: Filan #6, G-05-27N-08W  
Lodewick #11, O-30-27N-09W

Dear Paul:

The 1991 Bradenhead Tests and a review of our records indicate the referenced wells have casing failures. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity as soon as possible.

If you have any questions, you may call me at 334-6178.

Yours truly,

A handwritten signature in cursive script, appearing to read "Charles Gholson".

Charles Gholson  
Deputy Oil & Gas Inspector

xc: well file