Form 3160-5 (August 1999)

Name (Printed/Typed) MARY CORLEY

Signature

(Electronic Submission)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Expires: November 30, 2000

;.	Lease Serial No.	
	NMNM013860A	

		 ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	• •	
-	7.0 7	 A 11 - 44		- NI

FORM AI PROVED OMB NO. 1904-0135

Do not use this abandoned wel	6. If Indian, Allottee of	or Tribe Name		
SUBMIT IN TRIF	PLICATE - Other instruc	ctions on reverse side.	7. If Unit or CA/Agre	en ent, Name and/or No.
Type of Well     ☐ Oil Well	er		8. Well Name and No. RUSSELL LS 11	
Name of Operator     BP AMERICA PRODUCTION	Contact:	MARY CORLEY E-Mail: corleyml@bp.com	9. API Well No. 30-045-21264-0	00-S1
3a. Address P. O. BOX 3092 HOUSTON, TX 77253		3b. Phone No. (include area code) Ph: 281.366.4491 Fx: 281.366.0700	10. Field and Pool, or BLANCO	E cploratory
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description		11. County or Parish,	ar d State
Sec 25 T28N R8W NWNE 10: 36.63664 N Lat, 107.62856 W	90FNL 1650FEL	12335 P	SAN JUAN CO	UINTY, NM 
12. CHECK APPE	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF N	OTICE, REPORT, OR OTHE	R DATA
TYPE OF SUBMISSION		TYPE OF	ACTION	
	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off
☐ Notice of Intent	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
Subsequent Report     ■	☐ Casing Repair	■ New Construction	☐ Recomplete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon	□ Temporarily Abandon	
_	☐ Convert to Injection	☐ Plug Back	□ Water Disposal	
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f	ally or recomplete horizontally rk will be performed or provid to operations. If the operation romandonment Notices shall be final inspection.)  3G stop @ 1775'. PLUG: followed w/28 SXS Bumpst rate & circ. PLUG #3:	, give subsurface locations and measure the Bond No. on file with BLM/BIA soults in a multiple completion or recoiled only after all requirements, including #1: 2800' - 1775' W/36 SXS NI plug. TIH to 617'. PLUG #2: 170' - Surface w/72 SXS CMT	ed and true vertical depths of an peril.  Required subsequent reports shall be impletion in a new interval, a Form 31 ing reclamation, have been completed EAT CMT. Mix 8 SXS 617' - 450' w/5 SXS	e filed within 30 days 60-4 shall be filed once
14. I hereby certify that the foregoing is	Flectronic Submission	#14127 verified by the BLM Well	Information System	
С	Ear BD AMERIC	A PRODUCTION CO, sent to the rocessing by Steve Mason on 09	Farmington	

STEPHEN MASON PETROLEUM ENGINEER ACCEPTED Date 0!3/16/2002 Ap<u>proved By</u> Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office Farmington which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title

Date

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

09/10/2002

AUTHORIZED REPRESENTATIVE