

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM-0553184
2. NAME OF OPERATOR Dugan Production Corp.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 234, Farmington, NM 87401		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1905' FSL - 1853' FEL		8. FARM OR LEASE NAME Ojo-He-He
14. PERMIT NO.		9. WELL NO. 5
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6149' GR		10. FIELD AND POOL, OR WILDCAT WAW - Pictured Cliffs
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 33, T27N, R13W
		12. COUNTY OR PARISH San Juan
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	Completion <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>		(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-2-76

PBTD 1393'. Moved in and rigged up Farmington Well Service swabbing unit. Go International ran gamma-ray correlation and collar log. Swabbed fluid down to approx 800'. Perf w/one 2-1/8" glass jet/ft 1330-1340' and 1310-1315'. Swabbed well down, well kicked off making est 100-150 MCFGPD. Perf w/10 2-1/8" glass jets 1282-1291'. Made one swab run, no indication of additional gas or fluid entry.

7-7-76

Moved in and rigged up Farmington Well Service swabbing unit and ran 43 jts 1-1/4" OD 2.3# 10R IJ tbgs. TE 1354.26' set @ 1352' GR.

7-13-76

Treated well w/250 gals acid as follows: Pumped acid down tbgs, followed by 2 bbls wtr, pumped into formation down annulus, treating press 500 psi @ 1/2 BPM.

18. I hereby certify that the foregoing is true and correct

SIGNED

Thomas A. Dugan

TITLE

Engineer

DATE

7-22-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
FARMINGTON, N.M.