

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 080238

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Gee Gee

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 31, T27N, R12W

12. COUNTY OR PARISH

San Juan

13. STATE

NM

1. OIL ☐ GAS ☒ OTHER  
WELL WELL

2. NAME OF OPERATOR

Dugan Production Corp.

3. ADDRESS OF OPERATOR

Box 234, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface1850' FNL - 1850' FEL U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5853' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

8-10-76

Moved in and rigged up Morrow Drilling Company. Spudded 7-7/8" hole @ 3:00 PM.  
8-10-76. Drilled to 30'. Hole became wet, unable to finish surface hole w/air,  
injection pump not working.

8-11-76

Finished drilling 7-7/8" surface hole to 36'. Ran 1 jt 5-1/2" OD csg. TE 35.40'  
set @ 36' GR. Cemented w/7 sx cement. Job complete 12:00 noon 8-11-76.

8-17-76

TD 1290'. Finished drilling 4-3/4" hole. Ran electric log by Go International.  
Ran 42 jts 2-7/8" OD 6.5# J-55 8R EUE Class "B" tbg for csg. TE 1271.08' set @  
1270' GR. Good mud returns and reciprocated pipe during operations. Cemented  
w/90 sx BJ 2% Lodense. Bumped plug w/1500 psi, released to 800 psi. Shut in.  
Hydro-tested pipe to 4000 psi - held OK. POB 11:45 AM 8-17-76.

18. I hereby certify that the foregoing is true and correct

SIGNED

Thomas A. Dugan

TITLE

Engineer

DATE

8-20-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side