F-37-2-11-8W

TABULATION OF DEVIATION TEST GREAT LAKES CHEMICAL CORPORATION HAMMOND WELL NO. 5

SAN JUAN COUNTY, NEW MEXICO

| DEVIATION | DEPTH |
|----------------------------------|----------------|
| 1° 3/4° | 238' 780' |
| 3/4 ⁰ | 1285' |
| 2 ⁰ 2 ⁰ | 1468' |
| 1 1/20 | 1968' 2249' |
| 1 1/2 ⁰ | 2792' |
| 1 1/40 | 3292' |
| 3/4° _3/4° | 3715' 4237' |
| 10 | 4691' |

AFFIDAVIT

This is to certify that the above deviation tests are correct to the best of my knowledge.

W. E. Landry Area Manager

Minerals Management INc.

