4-USGS (Farming	ton) 1-File								
Form 9-331 (May 1963)	UNITE	STATES	SUBMIT IN TRIPLICAT		Form app Budget B		/ No. 42–R1424.		
(124) 2007	DEPARTMENT OF THE INTERIOR (Other instructions on verse side)			5. LE.	ASE DESIGNAT	ION AN	D SERIAL: NO.		
	GEOLOG	ICAL SURVEY		N	м 11580	<i>:</i> .	영화 취 - 연락=		
CLIN	DRY NOTICES A	ND PEPORTS C	N WELLS	6. IF	INDIAN, ALLO	TTEE O	R TRIBE NAME		
			nck to a different reservoir.			ं	<u> </u>		
	Use "APPLICATION FOR	PERMIT—" for such pr	oposals.)		<u> </u>	<u> </u>	9 × 5 5		
1. OIG CT GAS				7. UN	IT ACREEMENT	MAME E			
	X OTHER				2455	<u> </u>	<u> </u>		
2. NAME OF OPERATOR Dugan Production Corp.					RM OR LEASE	akan E	# E E		
3. ADDRESS OF OPERATOR					K = = = =		<u> 8 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 </u>		
	234, Farmington,	NM 87401			8 11.70	7 5	Line of the control o		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*					IELD-AND-POOL	V	/ILDCAT 5		
See also space 17 below.) At surface					AWEAPic	ture	ed Cliffs		
1850' FNL - 990' FEL					EC., T., R., M.,	OR BLK			
					SURVEY OR A	EEA.	100 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	•			S	ec. 19 1	27N	_R13w		
14. PERMIT NO.	15. ELEV	TIONS (Show whether DF,	BT, GR, etc.)	12. c	OUNTY- OR PAR	use 1			
		6094	GR	S	angJuan	<u> </u>	NM = 3		
16.	Check Appropriate	Box To Indicate N	ature of Notice, Report, or	Other D)atā. ti a a	5			
NOTICE OF INTENTION TO:					놀림축투	ŝ	ziis Siiri		
		[<u>-</u> -			4 7 4 2	9291			
TEST WATER SHUT-O	<u> </u>		WATER SHUT-OFF		S REPAIRIE	.5	[#] 솔릭 증 다.		
FRACTURE TREAT	MULTIPLE C	OMPLETE -	FRACTURE TREATMENT		Salteein A A A A A	್			
SHOOT OR ACIDIZE	ABANDON* CHANGE PLA	Va	shooting or acidizing [(Other) Long Str	ing	S ABANDON	TEMAIK!			
REPAIR WELL (Other)	CHANGE PLA		(Note: Report resu	lts of mul	tiple completi	on on	Well		
	COMPLETED OPERATIONS (C	learly state all pertinent	details, and give pertinent dat						
proposed work. If nent to this work.)	well is directionally drille	l, give subsurface locati	details, and give pertinent dat ons and measured and true ver	tical depth		• • •			
			•	22.2	nd th nict) frank da ha	Indi	ling mell		
				. 3		, t	交易其中 5		
				SINA		55	Live the		
	en e			avos	: Day tour mon	ederal or	TO THE SECOND		
	TD 1475'		## 10m 11 C		*:		·		
3 -2 -78	Ran 48 jts 2-7/8" OD 6.4# J-55 10R NUE tbg for csg. Hydro- tested to 4000 psi - OK. Preflushed hole w/100 gal mud sweep.								
Cemented w/75 sx 2% Lodense w/1/4# cello flake p by 50/sx neat cement w/1/4# cello flake per sx.					•				
	and had good mud returns while cementing. Lost					•			
after dropping plug. Bumped plug w/2300 psi - 1						000			
	psi. POB 4:15		Francis In a						
	•	•			•				
				•	• •		•		
•									
			18 July 18		# = I = I	~ :	552		
			13/2	.]	n irobanda i golda e i golda i	applicabl	dings and displaying the control of		
		*	1 NOR I	- []	nobunda nicthod cent forthod cent foot dot		24. 24. 24. 24. 24. 24. 24. 24. 24. 24.		
•			\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		da ed d no om S	specific to applife	9 5		
	: 1		OIL DIS.		nepochion to almost a deport a deport in a depochion booking the problem is a depochion booking a	100 100 100 100 100 100 100 100 100 100	oral T burs burs burs trans		
					than of alma openia and the fixe noth the fixe noth	اردو د الرا			
18. I hereby certify that the toyegoing is true and correct						F	NY E		
SIGNED (). 1. Million TITLE Petroleum Engineer					DATE.	3-9-	·78.3 =		
Thomas A. Dugan						<u> </u>	2		
(This space for Fede	ral or State office use)				ontice phragonal contice conti	or b tem	12 TO		
APPROVED BY	_//	TITLE		 -	collibra n collibra n configuration configuration	<u> </u>	<u> </u>		
CONDITIONS OF A	PPROVAL, IF ANY:	•	* * * * * * * * * * * * * * * * * * *	· time J	n n Nuit ads con	E.	70GS 20 Cu 12 J		
			MAR 11	1978	•				