

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 11580
2. NAME OF OPERATOR Dugan Production Corp.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 234, Farmington, NM 87401		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790' FSL - 1850' FEL		8. FARM OR LEASE NAME KR
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6061' GR	9. WELL NO. #3
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data.		10. FIELD AND POOL, OR WILDCATS WAW Pictured Cliffs
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*		11. SEC. T, R, M, OR BLK. AND SURVEY OR AREA Sec. 20 T27N, R13W
		12. COUNTY OR PARISH San Juan
		13. STATE NM

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>	WATER SHUT-OFF	<input checked="" type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>				

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

3-3-78 Moved in and rigged up Morrow Drlg Co. Spudded 7-7/8" hole @ 10:15 a.m. Drlg to 37'. Ran 1 jt 5-1/2" OD 14# ST&C csq. TE 36.02' set @ 37' GR. Cemented w/6sx Job complete 11:45 a.m.



18. I hereby certify that the foregoing is true and correct

SIGNED Thomas A. Dugan TITLE Petroleum Engineer

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

DATE 3-9-78

DATE

MAR 10 1978