

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other
well well

2. NAME OF OPERATOR
Tenneco Oil Company

3. ADDRESS OF OPERATOR
720 S. Colorado Blvd., Denver, CO 80222

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1850'FNL & 2510'FEL, Unit G
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☒
☒
☒
☐
☐
☐
☐
☐
☐

5. LEASE ~~USA-NM-03549~~

USA-SF-080112

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Gooch

9. WELL NO.

2

10. FIELD OR WILDCAT NAME
Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 29, T28N, R8W

12. COUNTY OR PARISH San Juan

13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
5887'GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9/26/79 - 9/28/79

MIRUPU. NUBOE. Pressure tested csg to 3500 PSI for 15 min. - held OK. Spotted 500 gals. 7 1/2% HCL acid. Ran electric logs. Perforated the Dakota formation from 6573'-6590', 6656'-6660', 6674'-6682', w/2JSPF. Acidized w/1500 gals. 15% HCL acid @42 BPM & 2800 PSI. Frac'd well w/80,000 gals 30# crosslinked Versagel & 80,000# 20/40 sand & 215,000# sand. Air-50 BPM @ 2500 PSI. ISIP-2900 PSI. Ran 2 3/8" tubing & set @ 6578'. RDMOCU

RECEIVED

OCT 09 1979

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

OCT 15 1979

OIL COAL COM.
DIST. 3

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Admin. Supervisor

DATE

Set @ Ft.

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: