Form 9-331 Dec. 1973

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLIETE CHANGE ZONES ABANDON* (other)

Form Approved.

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Dec. 1973	Budget Bureau No. 42–R1424
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE SF 078499
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form 'or proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas X other	Tapp
well well other 2. NAME OF OPERATOR	9. WELL NO. 3A
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	10. FIELD OR WILDCAT NAME Blanco Mesa Verde 11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA Sec. 15,T-28-N, R-8-W N.M.P.M.
AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEFTH:	12. COUNTY OR PARISH 13. STATE San Juan New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD 6389' GL

(NOTE: Report results of multiple completion or zone

change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SUBSEQUENT REPORT OF:

Spudded well. Drilled surface hole. Ran 5 joints 9 5/8", 36#, K-55 surface 12-8-79: casing 209' set at 221'. Cemented w/224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes.

Subsurface Safety Valve: Manu. and Type	Set @ Ft. Drilling Clerk _{DATE} December 10, 1979
(This space for F	Federal or State office use) DATE

*See Instructions on Reverse Side

