FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)

(NOTE: Report results of multiple completion or zone

change on Form 9-330)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE NM 011808
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME
1. oil gas X other	Marshall
	9. WELL NO.
2. NAME OF OPERATOR	1E
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota
Box 289, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 14, T-27-N, R-9-W
below.)	N.M.P.M.
AT SURFACE: 960'S, 1070'E AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	San Juan New Mexico
	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
	15. ELEVATIONS (SHOW DF. KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6044' G1
TEST WATER SHUT-OFF	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates. including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-4-79: Spudded well. Drilled surface hole.

Ran 5 joints 8 5/8", 32.3#, H-40 surface casing 209' set at 222'. Cemented 12-5-79: w/165 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes.

Subsurface Safety Valve: Manu. and Type ___ _ Set @ 18. I hereby dertify that the foregoing is true and correct TITLE Drilling Clerk DATE December 6, 1979 SIGNED & (This space for Federal or State office use) APPROVED BY DATE CONDITIONS OF APPROVAL IF ANY:

*See Instructions on Reverse Side