UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on	Wells
1. Type of Well GAS	5. Lease NumberNM 010746. If Indian, All.orTribe Name
2. Name of Operator	7. Unit Agreement Name Huerfano Unit
Meridian Oil Inc.	8. Well Name & Number Huerfano Unit #275
3. Address & Phone No. of Operator Box 4289, Farmington, NM 87499 (505)326-9700	
4. Location of Well, Footage, Sec, T, R, M. 800'S, 800'E Sec.36, T-27-N, R-11-W, NMPM	10.Field and Pool Basin Dakota 11.County and State San Juan County, NM
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NO	OTICE, REPORT, OTHER DATA
Notice of Intent Abandonment	F Action Change of Plans New Construction Non-Routine Fracturing Water Shut Off
Final Abandonment Altering Casing Other - Repair	g Conversion to Injection
13. Describe Proposed or Completed Operations	
Meridian's records indicate that the following wrepair the casing failure:	work was completed to
03-22-88 MOL&RU. Isolated csg failure between retainer.	n pkr & existing cmt
03-23-88 Squeezed 50 sx cmt (59 cu.ft.) into f 03-24-88 TIH, tag cmt plug. Drld out plug & C csg, ok. Stung back into retainer. production.	CO to cmt retainer. PT
	RECEIVED JUL 3 1 1991
	OIL CON. DIV.
14. I hereby certify that the foregoing is true	
Signed Signed Title Regulatory	Affairs Date/-//.
(mbig appear for Fodoral or Chata office use)	ACCEPTED FOR RECORD
(This space for Federal or State office use)	JUL 21 1931
APPROVED BY TITLE CONDITION OF APPROVAL, IF ANY:	FAhamoron nasounce mitch
and the second of the second o	вү 5~~