UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

925 Greenville Ave. Dallas, Texas 75206

Dec. 1973	Budget Bureau No. 42-R1424 5. LEASE NM 33023		
UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)			
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
	7. UNIT AGREEMENT NAME		
	8. FARM OR LEASE NAME JK		
1. cil gas X other	9. WELL NO.		
2. NAME OF OPERATOR	1		
BILLY J. KNOTT	10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR #850 One Energy Square	WAW Fruitland-PC		
Greenville Ave. Dallas, Texas 75206	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREASec.30 - T27N - R12W		
below.) AT SURFACE: 1850' FNL - 1520' FWL	N. M. P. M. 12. COUNTY OR PARISH 13. STATE		
AT TOP PROD INTERVAL.	San Juan New Mexico		
AT TOTAL DEPTH: Same	14 ADLNO		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. AFI NO. Chiago B. 6 1/4/4/ 2006 - Carrier		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
DESCRIPTION APPROVAL TO CURRENT REPORT OF	5889 KB 5885÷GL 第二章第45		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF L	50 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		
SHOOT OR ACIDIZE	NOTE: Report results of multiple completion or zone change on Form 9–330.)		
REPAIR WELL	(NOTE: Report results of multiple completion or zone		
PULL OR ALTER CASING	Change on Form 9-330.)		
CHANGE ZONES	의 1980년 원 - [월급일] - 연 환입되었는 걸.		
ABANDON* U. C. CEOLOG	COAL SUBVEY TO SEE STATE TO		
	UN, N. M. T. Wilder F. Salar F.		
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	e all pertinent details, and give pertinent dates,		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 11-30-79 the above captioned well was spudded at 4:00 PM. A 9 7/8" surface hole was rotary mud drilled to a depth of 100' KB which was reached at 11:30 AM on 12-1-79 ran approx. 91' of 20#, K-55, 7" surface casing set at 95' KB. Cemented surface casing with 50 sacks of Class "B" cement w/2% CaCl. Cement circulated to the surface, plug down at 1:00 PM.

Subsulface Safety valve, Mailu, allu Type		JEL	<u> </u>		_ r
18. I hereby certify that the foregoing is true and correct) 12.00.0 10.00.0		
SIGNED ASSITON B. Verentile Agent	DATE _	7-3-80			
Ashton B. Geren. Jr.			100		
(This space for Federal or State office use)		144.9	44		
APPROVED BY TITLE	DATE		W =1		
CONDITIONS OF APPROVAL, IF ANY:		3.5	este	n ኮስይ ኮቹ	:cai

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

3 1980 JUL

FARMINGTON DISTRICT