5-USGS (Farmington) 1-File	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES  DEPARTMENT OF THE INTERIOR	5. LEASE 1.3.7913 3.3.7
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME La Lee Ann
1. oil gas well other  2. NAME OF OPERATOR	9. WELL NO. #3
Dugan Production Corp.  3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME WAW FR PC
Box 208, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	Sec 28 T27N R13W
AT SURFACE: 990' FSL - 1650' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE  San Juan NM
AT TOTAL DEPTH:  16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. (1915)
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6097' GL
TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent	Rectionally dillied. Sive appartace locations and
4-4-80 Ran 46 jts 2-7/8" OD 6.5# J-55 8R EUE the 1382' GL. Had good circulation and reconcirculated trace of cement to surface. w/1/4# cello flake per sx followed by 50 flake per sx. Bumped plug w/1500 psi - POB 1:00 p.m. 4-4-80	iprocated pipe while cementing. Cemented w/75 sx 2% Lodense O sx class "B" neat w/1/4# cello
Subsurface Safety Valve: Manu. and Type	BY St @APR 1980 Ft.
18. I hereby certify that the foregoing is true and correct	OIL CONE COM.
SIGNED THE Petroleum Eng Thomas A. Dugah  (This space for Federal or State off	DATE 4-7-00
·/	
APPROVED BY	