

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other

2. NAME OF OPERATOR

Dugan Production Corp.

3. ADDRESS OF OPERATOR

Box 208, Farmington, NM 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 990' FSL - 1550' EEL

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDON*

(other)

SUBSEQUENT REPORT OF:

RECEIVED
10 1988

MAY 10 198

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-2-80 Rigged up Farmington Well Service swabbing unit. Southwest
Survys ran GR-CCL. Swabbed 2-7/8" casing down to 900'. Perforated
from 1332-1342', 10 holes, 1 SPF with 2-1/8" jets. Swabbed
well down. No indication of gas or fluid entry. Waiting on acid
job.

5-3-80 MI & RU Western Co. Acidize well using 260 gal 15% HCl. Breakdown
pressure 2000 psi. Pumped 5 BPM. Average injection rate 3 BPM.

ISDP 300 psi. Swabbed well down. No indication of gas or fluid entry.

Subsurface Safety Valve: Manu. and Type

18. I hereby ~~certify~~ that the foregoing is true and correct

SIGNED Sherman E. Dugan TITLE Agent

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

NMOC