

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☐ gas well ☒ other ☐

Northwest Pipeline Corporation

P.O. Box 90, Farmington, N.M. 87401

AT SURFACE: ~~1800' FEL & 1750' SAL~~
AT TOP PROD. INTERVAL: Same as above
AT TOTAL DEPTH: Same as above

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>
(other) _____	<input type="checkbox"/>

Correction Code

□ □ □ □ □ □ □

RECEIVED

MAR 25 1961

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Correction: Perfed 22 holes from 4000' to 4478' instead of reading perfed 22 holes from 4000' to 4978'.

Subsurface Safety Valve: Manu. and Type

Set @ _____ ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Donna H. Brace TITLE Production Clerk

DATE _____

3-23-81

FARMINGTON DISTRICT

(This space for Federal or State office use) BY _____

APPROVED BY

TITLE

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NAOCC

djb/

***See Instructions on Reverse Side**