
UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



Sundry Notices and Reports on Wel	ls
1. Type of Well GAS	 5. Lease Number SF-077874 6. If Indian, All. or Tribe Name 7. Unit Agreement Name
 Name of Operator Southland Royalty Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700 Location of Well, Footage, Sec., T, R, M 1610'FSL, 1070'FEL Sec.5, T-27-N, R-9-W, NMPM 	8. Well Name & Number Hanks #18M
Subsequent Report Plugging Back Casing Repair	tion _ Change of Plans _ New Construction _ Non-Routine Fracturing _ Water Shut off _ Conversion to Injection
Meridian Oil has evaluated this wellbore and is a shut in because the well is unable to be such time when additional mainline capace pressure decrease, the wellbore will be productivity.	cick line pressure. At city is increased and
SEE AT CHED FOR CONDITIONS OF APPROVAL OIL CON. DIV. DIST. 3 THIS APPROVAL EXPIRES APR 2 0 1994	RECEIVED BLM 93 MAY 11 PM 2: 10 070 FARMINGTON, NM
14. I hereby certify that the foregoing is true and of Signed Man Mulling (MP) Title Regulatory At	
(This space for Federal or State Office use) APPROVED BY Title CONDITION OF APPROVAL, if any:	APPROVED MAY 13 1993
NMOCD	DISTRICT MANAGER



UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

CONDITIONS OF APPROVAL:

This Shut-In approval is contingent upon conducting a casing integrity test by _3FP 15 1993 . Mark Kelly with the Farmington Office is to be notified at least 48 hours prior to conducting the casing integrity test (505-599-8907). If the casing test fails, you will be required to submit your plans to repair the casing or plug and abandon the well.

Office Hours: 7:45 a.m. to 4:30 p.m.

