surface restoration is completed.

5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR

DEPAF	RTMENT OF THE INTERIOR	NM-33035	
	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
		N/A	
SUNDRY NOT	ICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
	proposals to drill or to deepen or plug back to a differe C for such proposals.)	ntN/A	
reservoir. Use Form 9-331-	tor such proposals.)	O. FARM OR LEASE NAME	
1. oil gas well well	Other Dry Hole	Campbell	
	Dry Hore	9. WELL NO.	
2. NAME OF OPERAT		2	
Oxoco Produ		WAW Fruitland-Pict.Cliffs	
3. ADDRESS OF OPE			
A LOCATION OF WEL	5, Farmington, N.M. 87401 LL (REPORT LOCATION CLEARLY. See space 1	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
below.)	LE (REPORT LUCATION CLEARLY, See space 1	Sec. 9, T27N-R13W, NMPM	
AT SURFACE: 79	90 ft. from S&W lines	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. IN		San Juan New Mexico	
AT TOTAL DEPTH:	same as above	14. API NO.	
	ATE BOX TO INDICATE NATURE OF NOTICE		
REPORT, OR OTHI	ER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)	
		5964 Gr.	
REQUEST FOR APPROV	1		
TEST WATER SHUT-OF FRACTURE TREAT	' RÉCEN		
SHOOT OR ACIDIZE		V have bad	
REPAIR WELL		CO (NOTE: Report results of multiple completion or zone	
PULL OR ALTER CASII	NG 📙	3 335.7	
MULTIPLE COMPLETE CHANGE ZONES	H U. S. GEOLOGICA	L SURVEY	
ABANDON*	FARMINGTON,	N. M.	
(other)			
45 0500005 00000		,	
including estimated	SED OR COMPLETED OPERATIONS (Clearly st d date of starting any proposed work. If well is	tate all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and	
measured and true	vertical depths for all markers and zones pertin	directionally drilled, give subsurface locations and lent to this work.)*	
May 13, 198	2Disconnected sonarator	Rigged up Farmington Well	
Service uni	t. Unseated packer and pul	led 1½" tubing and packer.	
Klgged up W	OODCO Cementing Service tr	tuck and numbed 55 cacks (65 as	
ft.) neat C	Rigged up Woodco Cementing Service truck and pumped 55 sacks (65 cu. ft.) neat Class B cement into 2 7/8" tubing, cementing to surface.		
Shut in wel	1 with valve on wellhead.	Cleaned location, filled and	
tamped pits	 Dug 10 ft, cellar around 	l wellhead.	
May 14, 198	2Cut off wellhead, 7" su	rface casing and 2 7/8"	
production	casing / it. below surface	e level. Welded %" steel plate	
over casing	stubs. Filled and tamped	cellar and cleaned and leveled	
location. W	ell plugged and abandoned.		
	E P A	RIMER	
	ID) E G	EIVEM	
Subsurface Safety Valve	in!	Ft.	
	1/1/	1 0 7 1985	
18. I hereby certify that	t the foregoing is true and correct		
SIGNED	SOEET TITLE AGOTL C	ON. DIV-5/17/82	
	_	NCT 3	
•	(This space for Federal or State		
APPROVED BY	TITLE	DATE APPROVED	
Approved as to plugging of Liability under hand	. •	APPROVED AS AMENDED	
		_	
surface restoration is com-	-1	inn na 1985	

*See Instructions on Reverse Side

JAN 04 1985 [Val.], Stan McKee M. MILLENBACH AREA MANAGER