PEL 2 9 1897

14 pproved

Meter Number:94618
Location Name:RUSSELL 3E
Location:TN-28 RG-08
SC-25 UL-I
2 - Federal
NMOCD Zone:OUTSIDE

Hazard Ranking Score:00

OIL COM. DIV.

### RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone  $10^{-9}$  to  $10^{-13}$  cm/sec Shale  $10^{-12}$  to  $10^{-16}$  cm/sec Clay  $10^{-12}$  to  $10^{-15}$  cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.



# FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: 94618 Location: Russell 3E  Operator #: 0203 Operator Name: Amoro P/L District: Blanco  Coordinates: Letter: Section 25 Township: 28 Range: 8  Or Latitude Longitude  Pit Type: Dehydrator Location Drip: Line Drip: Other:  Site Assessment Date: A 44 Area: 13 Run: 42						
SITE ASSESSMENT	NMOCD Zone:       Land Type:       BLM       ☒ (1)         (From NMOCD       State       ☐ (2)         Maps)       Inside       ☐ (1)       Fee       ☐ (3)         Outside       ☒ (2)       Indian       ☐         Depth to Groundwater       ☐ (1)       ☐ (1)       ☐ (2)         Less Than 50 Feet (20 points)       ☐ (1)       ☐ (2)         Greater Than 100 Ft (0 points)       ☒ (3)						
	Wellhead Protection Area:  Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source? ☐ (1) YES (20 points) ☒ (2) NO (0 points)						
	Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) (1) 200 Ft to 1000 Ft (10 points) (2) Greater Than 1000 Ft (0 points) (3) Name of Surface Water Body						
	(Surface Water Body : Perennial Rivers,Major Wash,Streams,Creeks, Irrigation Canals,Ditches,Lakes,Ponds) Distance to Nearest Ephemeral Stream ☐ (1) < 100'(Navajo Pits Only) ☐ (2) > 100'						
	TOTAL HAZARD RANKING SCORE: POINTS						
RKS	Remarks: Redline & Vula - Durile  Spits. Will close I. Pit dry. Deby still onpit, & connected to meter house. Does not						
REMARKS	appear to be operating. Deby not transferred to operator according to Deby Book  PLSH-IN						

Date

## FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL	Meter: 94618 Location: Russell 3E  Coordinates: Letter: I Section 25 Township: 28 Range: 8  Or Latitude Longitude  Date Started: 8-4-94 Run: L3 42
FIELD OBSERVATIONS	Sample Number(s): MK 227  Sample Depth: Feet als lad
CLOSURE	Remediation Method:  Excavation
REMARKS	Remarks: <u>FPNC lives Not Ranked Soil Brown Slight</u> Hyprocarbon odor Mit sandstone 3'  Signature of Specialist: <u>Margon Xillian</u>



# FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

## SAMPLE IDENTIFICATION

				1-5-15		
SAMPLE NUMBER:	Field ID		Lab ID			
-	MK 22			945848		
MTR CODE   SITE NAME:   SAMPLE DATE   TIME (Hrs):	9-4-91	94618		1451		
SAMPLED BY:	8 9 9 9 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4		1/A 7/9/44 N/A			
DATE OF TPH EXT.   ANAL.:						
DATE OF BTEX EXT. ANAL.:						
TYPE   DESCRIPTION:	VG		Brown course sand			
REMARKS:						
	F	RESULTS				
	DEQUE T	UNITS		QUALIF	IEDS	
PARAMETER	RESULT UN	UNITS	DF	Q	M(g)	V(mi)
BENZENE		MG/KG				
TOLUENE		MG/KG				
ETHYL BENZENE		MG/KG				
TOTAL XYLENES		MG/KG				
TOTAL BTEX		MG/KG				2 (1
TPH (418.1)	6160	MG/KG		ļ	1.14	L28
HEADSPACE PID	רד	PPM		<u> </u>		
PERCENT SOLIDS	95.8	%				
The Surrogate Recovery was at Narrative:	- TPH is by EPA Method 4	118.1 and BTEX is by EP % for this samp		C was accer	otable.	
OF = Dilution Factor Used Approved By:			Date:	s/r/a	4	

#### Test Method for Oil and Grease and Petroleum Hydrocarbons in Water and Soil

74/08/09 15:04

Sample identification 945848


Initial mass of sample, g 1.140

Volume of sample after extraction, ml @3.000

Petroleum hydrocarbons, ppm 3157.417

Net absorbance of hydrocarbons (2930 cm-1)

: .440



Topial good.

ILLEGIBLE