DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE NM-04202
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME Jackson Com
1. oil gas will other	9. WELL NO.
2. NAME OF OPERATOR Tenneco Oil Company 3. ADDRESS OF OPERATOR Box 3249, Englewood, CO 80155	10. FIELD OR WILDCAT NAME Basin Dakota 11. SEC., T., R., M., DR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 400' FSL, 1790' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	AREA Sec. 9, T28N, R9W 12. COUNTY OR PARISH 13. STATE San Juan NM 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6612 GR
REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES SUBSEQUENT REPORT OF: OCT V SUBSEQUENT REPORT OF:	1982
MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	N/ S
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stational including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertinents.)	ate all pertinent details, and give pertinent dates directionally drilled, give subsurface locations and ent to this work.)*

10/6/82: Mix mud to 30% LCM, lost 800 bbls total. Wash 400' to btm. Resume drlg.
10/7/82: Reach csg pt @ 9:00 am, 10/7/82. Sht trip, C&C, LDDP. RU & run 145 jts 7" 23#
K-55 S<&C (5828') set @ 5815', FC @ 5771', DV @ 2042'. Circ, full rtns. Cmt lst stage w/200 sx Cl-B (236 CF)+ 2% CaCl₂ + 1/4#/sx celloflake. Lost circ w/78 bbls left to be displaced. No rtns for rest of lst stage. PD w/1500# @ 9:00 pm, 10/7/82. Open DV, circ & WOC, cmt 2nd stage w/200 sx Cl-B (412 CF) + 2% D-79 + 2% CaCl₂ + 1/4#/sx celloflake, tail w/59 CF Cl-B + 2% CaCl₂ + 1/4#/sx celloflake. PD w/3,000 psi @ 1:30 am, 10/8/82. Circ 20 bbl preflush, no rtns after that, set slips w/90,000# & cutoff. NUBOP & test to 1,000 psi 30 min, ok. WOC.

Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct Lewise Wilson Production AnalystoATE October 15, 1982 (This space for Federal or State office use) DATE . ASCEPTED FOR RECORD OCT 10 1982 *See Instructions on Reverse Side FARMINGT SM

NMOCC