

N

30-045-25438

8-25-82

F. Loc. 790/N; 990/W Elev. 5856 GL Spd. Comp. TD PB

Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @
Csg. Perf. Prod. Stim.

T
R
A
N
S

I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR Grav. Ist Del. s

TOPS		NiTD X	Well Log	TEST DATA							Ref.No.
Kirtland		C-103	Plat X	Schd.	PC	Q	PW	PD	D		
Fruitland		C-104	Electric Log								
Pictured Cliffs			C-122								
Cliff House		Ditr	Dfa								
Menefee		Datr	Dac								
Point Lookout		160									
Manco											
Gallup											
Sanostee											
Greenhorn											
Dakota											
Morrison											
Entrada											

P
o Beautiful Moun.
o Miss. Ext Co. SJ S 32 T 27N R 19W U D Oper. Petroleum Energy Inc. Lso. Navajo 32

No. 3

Navajo 32 #3

D-32-27N-19W

PETROLEUM ENERGY INC.

Caller Service 4104
Farmington, New Mexico 87499

SEP 07 1983

CERTIFIED

Petroleum Energy, Inc.
P.O. Box 2121
Durango, Colorado 81301

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 3-32 Navajo, NW $\frac{1}{4}$ NW $\frac{1}{4}$ sec. 32, T. 27 N., R. 19 W., San Juan County, New Mexico, lease NOO-C-14-20-4158. As discussed with Larry Sweringen of your company on September 2, 1983, the subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, it will presume that no construction activities have occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in assessment of liquidated damages.

Sincerely yours,

Bill Bingham
acts Area Manager

Enclosure

cc: NMOCC

RECEIVED
SEP 8 - 1983
OIL CON. DIV.
DIST. 3

ABANDONED