

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other
-
2. NAME OF OPERATOR
Tenneco Oil Co.
-
3. ADDRESS OF OPERATOR
Box 3249, Englewood, CO 80155
-
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1520' FSL, 1025' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
-
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

SUBSEQUENT REPORT OF

TEST WATER SHUT-OFF	☐
FRACTURE TREAT	☐
SHOOT OR ACIDIZE	☐
REPAIR WELL	☐
PULL OR ALTER CASING	☐
MULTIPLE COMPLETE	☐
CHANGE ZONES	☐
ABANDON*	☐
(other) _____	☐

Temperature _____

(other) Temperature Survey

STUDENT REPORT OF

RECEIVED

10 1983

FEB 10 1964
U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

5. LEASE
SF-079319
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Schwerdtfeger A
9. WELL NO.
2E
10. FIELD OR WILDCAT NAME
Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 31, T28N, R8W
12. COUNTY OR PARISH | 13. STATE
San Juan | NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
6411' GR

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Attached is a copy of the temperature survey run on the above-referenced well to determine top of cement behind the 7" casing. Top of cement is at 750', as reported by Sundry Notice on November 30, 1982.

RECEIVED
FEB 15 1983
OIL CON. DIV.
DIST. 3
Set @

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Leenise Wilson TITLE Production Analyst DATE February 7, 1983

(This space for Federal or State office use)

APPROVED BY JAE
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

ACCEPTED FOR RECORD

***See Instructions on Reverse Side**

FEB 1 1993

FARMINGTON DISTRICT

NMOC

FORM 432-2

WILSON

SERVICE COMPANY

TEMPERATURE SURVEY

COMPANY Tenneco Oil Co.
WELL 2X 2E LEASE Swerdtfeger A
COUNTY San Juan STATE New Mexico
SEC. 31 TWP. 28N RGE. 8W

APPROX. TOP CEMENT 750'

Survey Begins at 100' Ft. Ends at 3001' Ft.
Approx. Fill-Up _____ Max. Temp. _____
Log Measured From KB Run No. 1

Casing Size	Casing Depth	Diam of Hole	Depth
<u>7"</u> from _____ to _____		from <u>8 3/4"</u> to _____	
from _____ to _____		from _____ to _____	


Date of Cementing 1/22/82 Time 9:00 PM
Date of Survey 1/23/82 Time 3:00 AM
Amount of Cement As Per Report.


Recorded by Mahaffey Witnessed by _____

REMARKS OR OTHER DATA

Float at 3050'.

TEMPERATURE IN DEGREES FAHRENHEIT





1200'

1300'

1400'

1500'

1600'

1700'


1800'

1900'

2000'

2100'

2200'



2200'

2300'

2400'

2500'

2600'

2700'

2800'

2900'

3000'

TD Surveyed 3001'