

MERRION OIL & GAS CORPORATION

Pete 1R  
Sec. 35, T27N, R12W  
San Juan Co., New Mexico

SLOPE TESTS

Depth

Hole Deviation

450'  
1100'

1/2°  
3/4°

RECEIVED  
APR 27 1984  
OIL CON. DIV.  
DIST. 3

State of New Mexico )  
County of San Juan ) ss

I, Steve S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 26th day of April, 1984.

Rolando Strange  
Notary Public

Not 28 1985