

OK

District I

State Of New Mexico

SUBMIT 1 COPY TO

P.O. Box 1980, Hobbs, NM

Energy, Minerals and Natural Resources Department

APPROPRIATE

District II

P.O. Drawer, Artesia, NM 88211

OIL CONSERVATION DIVISION

DISTRICT OFFICE

District III

P.O. Box 2088

AND 1 COPY TO

1000 Rio Brazos Rd. Aztec, NM 87410

Santa Fe, New Mexico 87504-2088

SANTA FE OFFICE

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORTOperator: Conoco Inc.Telephone: 505-324-5813Address: 3315 Bloomfield Hwy - Farmington, NM 87401

Facility Or:

Holloway Fed. #6E

Well Name

Location: Unit or Qtr/Qtr SecDSec 18

T

27N

R

11W

County

San JuanPit Type: Separator ☒Dehydrator ☐Other ☐Land Type: BLM ☒State ☐Fee ☐Other ☐Pit Location:
(Attach diagram)

Pit dimension:

length 15'width 15'depth 7'

Reference:

wellhead ☒other ☐

Footage from reference:

111'

Direction from reference:

340°

Degrees

East

of

☒ North☒ West☐ South

Depth To Ground Water:

(Vertical distance from
contaminants to seasonal
high water elevation of
ground water)

Less than 50 feet (20 points)

50 feet to 99 feet (10 points)

Greater than 100 feet (0 points)

Total

0

Wellhead Protection Area:

(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water sources)

Yes (20 points)

No (0 points)

Total

0

Distance To Surface Water:

(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)

Less than 200 feet (20 points)

(20 points)

200 feet to 1000 feet (10 points)

(10 points)

Greater than 1000 feet (0 points)

(0 points)

Total

0

RANKING SCORE (TOTAL POINTS):

0

Date Remediation Started: December 17, 1999 Date Completed: December 17, 1999
Remediation Method: Excavation: _____ Approx. cubic yards _____
(Check all appropriate sections)
Landfarm _____ Insitu Bioremediation _____
Other _____
Remediation Location: Onsite _____ Offsite _____
(ie. landfarmed onsite,
name and location of
offsite facility)
General Description Of Remedial Action: Took sample 3' below bottom of pit.

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit: Sample location Center of pit 3' below.

Closure Sampling: Sample depth 3' below bottom.

(if multiple samples
attach sample results
and diagram of sample
locations and depths) Sample date Dec. 17, 1999 Sample time _____

Sample Results

Benzene (ppm) .318

Total BTEX (ppm) 3.704

Field headspace (ppm) not taken

TPH 734

Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST
OF MY KNOWLEDGE AND BELIEF

DATE February 7, 2000

PRINTED NAME Shirley Ebert

SIGNATURE Shirley Ebert

AND TITLE Field Shear Specialist

EPA METHOD 8015 Modified
Nonhalogenated Volatile Organics
Total Petroleum Hydrocarbons


Client:	Conoco	Project #:	707003-120
Sample ID:	Center Pit Sep.	Date Reported:	12-28-99
Laboratory Number:	G651	Date Sampled:	12-17-99
Chain of Custody No:	7234	Date Received:	12-22-99
Sample Matrix:	Soil	Date Extracted:	12-22-99
Preservative:	Cool	Date Analyzed:	12-27-99
Condition:	Cool and Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	163	0.2
Diesel Range (C10 - C28)	571	0.1
Total Petroleum Hydrocarbons	734	0.1

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: **Holloway Fed. #6E Tank Drain Pit.**


Analyst


Review

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	Conoco	Project #:	707003-120
Sample ID:	Center Pit Sep.	Date Reported:	12-28-99
Laboratory Number:	G651	Date Sampled:	12-17-99
Chain of Custody:	7234	Date Received:	12-22-99
Sample Matrix:	Soil	Date Analyzed:	12-27-99
Preservative:	Cool	Date Extracted:	12-22-99
Condition:	Cool & Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
Benzene	318	1.8
Toluene	973	1.7
Ethylbenzene	237	1.5
p,m-Xylene	1,760	2.2
o-Xylene	416	1.0
Total BTEX	3,704	


ND - Parameter not detected at the stated detection limit.


Surrogate Recoveries:	Parameter	Percent Recovery
	Trifluorotoluene	100 %
	Bromofluorobenzene	100 %

References: Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: Holloway Fed. #6E Tank Drain Pit.


Analyst


Review

7234

ENVIROTECH INC.

5796 U.S. Highway 64
Farmington, New Mexico 87401
(505) 632-0615

After.

Date: 8/28/99

Operator: Will Helling

Lease Name: Holloway Fed #6E

Site Security
(Indicate North)

